




















PRODUCENT	ZDJĘCIE	SYBMOL	MODEL RADIOTELEFONU
MOTOROLA HYT KIRISUN		M4	MTX850, MTX850LS, MTX950, MTX960, MTX8250, MTX8250LS, MTX9250PRO5150, PRO5350, PRO5450, PRO5550, PRO5750, PRO7150, PRO7350, PRO7450, PRO7550, PRO7750, PRO9150, PTX780GP140, GP320, GP328, GP329, GP330, GP338, GP339, GP340, GP360, GP380, GP600, GP640, GP650, GP680, GP1280MTP700, MTP850 Ex, MTP810 Ex
		M5	Motorola Series: Ex500, EX600, GL2000, GP328plus, GP338plus, PTX760Plus GP344, GP388, PRO5150Elite RELM Series: RPV3000, 3600/RPU3000, 3600 HYT Series: TC380M/370M, TC780M, TC-780, TC610P Kirisun Series: PT7200, TC3000
		M6	Motorola Series: GP900, GP9000, HT1000, JT1000, MT2000, MTS2000, MT6000, MTX838, MTX900, MTX1000, MTX8000, MTX9000, MTX-LS, XTS2000, XTS2500, XTS3000, XTS3500, XTS5000/5100/7700 EF Johnson Series: 5100/5700 Series, 511X, 512X, 518X
		M7	XPR6300, XPR6350, XPR6500, XPR6550, APX7000.
		M8	Motorola MTP850
		M9	MTH650, MTH800, MTH850
		NK	Nokia Series: EADS THR880i
		NK1	THR9
	KENWOOD		K1
		K2	TK-280, TK-290, TK-380, TK-385, TK-390, TK-480, TK-481, TK-2041, TK-2140, TK-3140, TK-3148, TK3185

PRODUCENT	ZDJĘCIE	SYBMOL	MODEL RADIOTELEFONU
ICOM		S4	F30GT, F40GT, F50, F51, F60, F61, F30GS, F40GS, F41G, F31G, M88, M87, F70, F80, F3061, F4061, F70DT, F70T, F70DS, F70S, F80DT, F80T, F80DS, F80S, F3162, F4162
VERTEX		Y5A	VX-530, VX-537 Series
		Y6	VX-820, VX-821, VX-824, VX-829, VX-920, VX-921, VX-924, VX-929
SEPURA		SP1	SRP2000, SRP3000, SRH3500, SRH3800
		SP3	STP8000
TAIT		T1	TP8110, TP8115, TP8120, TP8135, TP8140, TP7110
M/A COM		MC1	M/A COM Series: JAGUAR 700P, P5100, P5130, P7100, P7130, P7150, P7170
		MC2	M/A COM Series: Prism/LPE200
HYTERA		H4	HYTERA Series: DMR PD 705, 785